National Transportation Safety Board FACTUAL REPORT Location/Time

NTSB ID: FTW02LA104	Aircraft Registration Number: N8942F					
Occurrence Date: 03/27/2002	Most Critical Injury: None					
Occurrence Type: Accident	Investigated By: NTSB					

Airport Proximity: On Airport	Distance From	Landing Facility:		Direction Fro	M Airport:
Fort Collins	со	80524	1205	MST	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Aircraft Information Summary

7 morate milorination Carminary								
Aircraft Manufacturer	Model/Series	Type of Aircraft						
Hughes	269A-1	Helicopter						

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 27, 2002, approximately 1205 mountain standard time, a Hughes 269A-1 helicopter, N8942F, was substantially damaged during a loss of control while hovering at the Fort Collins Downtown Airport, near Fort Collins, Colorado. The helicopter was registered to and operated by Freedom Flight Services LLC, of Berthoud, Colorado. The flight instructor and student pilot were not injured. Visual meteorological conditions prevailed, and a flight plan was not filed for the 14 Code of Federal Regulations Part 91 instructional flight. The local flight was originating at the time of the accident.

On the Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), and in a telephone interview with the NTSB investigator-in-charge, the instructor pilot reported that the wind was 2 to 3 knots at the time of takeoff, but forecasted to be gusty in the afternoon. Shortly after lifting off and while hovering at an altitude of approximately 3 feet, the helicopter with the student pilot at the flight controls, encountered a very strong gust of wind and began to "wobble." The instructor took control of the helicopter, "picking it up" to approximately 15 feet, when another gust of wind hit the helicopter, turning it sideways, and then downwind. The instructor stated he was attempting "get it on the ground, but the wind continued to drive the helicopter forward with excessive nose over tendency." With the tail rotor into the wind, creating a "high power demand and limited tail rotor authority," the helicopter "skipped" along the dirt 2 or 3 times. The helicopter traveled forward 60 to 70 yards, the right strut failed, and the helicopter rolled over on its right side. The instructor pilot reported the wind was gusting to 60 knots at the time of the accident.

At 1215, the reported weather at the Fort Collins-Loveland Municipal Airport, located 8 nm south of the accident site, was wind from 260 degrees at 13 knots gusting to 25 knots, visibility 10 statute miles, sky clear, temperature 19 degrees C, dewpoint minus 6 degrees C, and an altimeter of 29.76 inches of mercury.

An FAA inspector, who responded to the accident site, reported that all 3 main rotor blades were destroyed, the fuselage was bent, all Plexiglas broken, and the right skid was separated from the strut.

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW02LA104

Occurrence Date: 03/27/2002

AVIATION		Occurrence Type: Accident									
Landing Facility/Approach In	formation										
Airport Name		,	Airport ID:	Airport Eleva	ition	Run	way Used	Runwa	y Lengt	h R	unway Width
Fort Collins Downtown Airport 3N				4939 Ft	. MSL						
Runway Surface Type:											
Runway Surface Condition:											
Type Instrument Approach: NONE	<u> </u>										
VFR Approach/Landing: None											
Aircraft Information											
Aircraft Manufacturer			Model	/Series					Serial I	Number	
Hughes			269A	-1					1500	019	
Airworthiness Certificate(s): Norm	al										
Landing Gear Type: Skid											
Homebuilt Aircraft? No	Number of Seats:	2	Certifie	Certified Max Gross Wt.					Numbe	er of Engines: 1	
Engine Type: Reciprocating			-	Engine Manufacturer: Model/Series: Lycoming HIO-360-AIA							Rated Power: 160 HP
- Aircraft Inspection Information											
Type of Last Inspection			Date of Last Inspection Time Since Last Inspection					ection	n Airframe Total Time		
Annual			10/2001	10/2001 50 Hours						2270 Hours	
- Emergency Locator Transmitter (ELT) Information										
ELT Installed? Yes	ELT Operat	ed? Yes	3	ELT Aided in Locating Accident Site? No							
Owner/Operator Information											
Registered Aircraft Owner	Street A	Street Address 22748 Country Road 3									
Freedom Flight Services LLC			City Bethoud								Zip Code 80513
	Street A	Bethoud CO 80513 Street Address									
Operator of Aircraft											1
Same as Reg'd Aircraft Owner	City							State	Zip Code		
Operator Does Business As: Operator Designator Code:											
- Type of U.S. Certificate(s) Held: None											
Air Carrier Operating Certificate(s):	:										
Operating Certificate:	Operating Certificate: Operator Certificate:										
Regulation Flight Conducted Under	r: Part 91: Genera	al Aviati	on	·							
Type of Flight Operation Conducted	d: Instructional										
		FACTU	JAL REPO	RT - AVIAT	ION						Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW02LA104

Occurrence Date: 03/27/2002

AVIATION				Occurrence Type: Accident				1					
First Pilot	First Pilot Information												
Name						City	State Date of					Date of Birth	Age
On File						On File	File On File On File						42
Sex: M	ess				Certif	icate Num	nber: On File	•					
Certificate(s): Flight Instructor; Commercial													
Airplane Rating(s): Multi-engine Land; Single-engine Land													
Rotorcraft/Glider/LTA: Helicopter													
Instrument	Rating(s): Non	e											
Instructor Rating(s): Helicopter													
Type Rating	g/Endorsement fo	or Accident/Ir	ncident Aircra	ft? No			С	urrent B	iennial F	light Rev	view? 10	/2001	
Medical Ce	rt.: Class 2	Medica	al Cert. Statu	s: With Wai	vers/Limitat	ions			Dat	e of Last	Medical	Exam: 09/200	1
- Flight Tim	e Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Nigh	ıt	Actual	Instrument ual Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time		1500	400	60	50		100			1300			
Pilot In Con	nmand(PIC)												
Instructor		800	350										
Last 90 Day	/S	300	60										
Last 30 Day	/S	100	20										
Last 24 Hou	urs	8	8			<u> </u>							
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes			Toxico	logy Pe	rformed	? No	5	Second Pilot? Y	es
	n/Itinerary												
	ht Plan Filed: N	one											T
Departure F	Point						State	/	Airport I	dentifier	Depa	arture Time	Time Zone
Fort Collin	ns						СО	;	3V5		1205		MST
Destination							State Airport		Airport I	port Identifier			
Local Flight													
Type of Clearance: None													
Type of Airspace: Class G													
Weather Information													
Source of Briefing: Internet													
Method of	Briefing: Teleph	none											
				FACTUAL	REPORT	- AVIA	TION	1					Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: FTW02LA104

Occurrence Date: 03/27/2002

Occurrence Type: Accident

	FIYBOR	Occurrent	е туре.	Acciden	ıı							
Weather Information												
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Di	m Acci	dent Site	dent Site Direction From Accident Si			9	
FNL	1215	MST	4939 Ft.	MSL				8 NM	8 NM 180 De			Mag.
Sky/Lowes	st Cloud Condition: Clea	ar			•	Ft. A	.GL	Condition o	of Ligh	nt: Day		
Lowest Ce	iling: None		Ft.	AGL	Visibi	lity:	10	SM	Altir	meter:	29.76	"Hg
Temperatu	ıre: 19 °C	Dew Point:	-6 °C	Wind	Direction:	260			Der	nsity Altitude:	6756	Ft.
Wind Spee	ed: 13	Gusts: 25		Weath	ner Condt	ions at Acc	cident S	ite: Visual C	Condi	itions		
Visibility (F	RVR): Ft	. Visibility (R	VV)	SM	Intensity	of Precip	itation:					
Restriction	s to Visibility: None											
Type of Pr	ecipitation: None											
Accident	Information											
Aircraft Da	mage: Substantial		Aircraft Fir	e: None	e Aircraft Explos				losio	osion None		
Classificati	ion: U.S. Registered/U	J.S. Soil										
- Injury Su	mmary Matrix	Fatal Se	erious Mino	or	None	TOTAL						
First Pi	ilot											
Second	d Pilot						7					
Studer	nt Pilot				1		1					
Flight I	nstructor				1		1					
Check	Pilot											
Flight E	Flight Engineer											
Cabin /	Cabin Attendants											
Other (Other Crew											
Passer	ngers											
- TOTAL A	ABOARD -				2		2					
Other (Ground						7					
- GRANI	O TOTAL -				2 2							

National Transportation Safety Board

FACTUAL REPORT AVIATION

Occurrence Date: 03/27/2002

Occurrence Type: Accident

Admir	nistrative	Information

Investigator-In-Charge (IIC)

Thomas M. Little

Additional Persons Participating in This Accident/Incident Investigation:

James Hopkins Aviation Safety Inspector Federal Aviation Administration 26805 East 68th Avenue, Suite 200 Denver, CO 80249